# Surface Pack Instructions

3-port

6-port
(shown throughout)



**Tools**

Also refer to applicable outlet termination instructions for additional required tools.

**1a** Disassemble packaged parts




| BOM ID | Description | Qty |
|---|---|---|
| 1 | Box label cover | 1 |
| 2 | Box label | 1 |
| 3 | Port label cover | 3 |
| 4 | Port label | 3 |
| 5 | Top cover | 1 |
| 6 | Base | 1 |
| 7 | Securing Screw | 1 |
| 8 | Cradle Bracket | 1 |
| 9 | Tie wrap | 1 |

**1b**

## Cable prep. if conduit system is used




**2a** Measure, mark, & strip cables

Terminate desired MAX series compatible outlets



**Refer to applicable instructions included with product or listed on line:**

*www.siemon.com/us/download/installation.asp*

- *Z-MAX or*
- *Punch-down MAX or*
- *TERA 4-pair outlet*

**2b**




**3**




**4**

# Surface Pack Instructions












*To ensure you have the latest revision to this document, please visit: http://www.siemon.com/us/download/installation.asp#mp*

**To assist safe installations, comply with the following:**

A. Use caution when installing or modifying telecommunications circuits.
B. Never touch uninsulated wire terminals unless the circuit has been disconnected.
C. Never install this device in a wet location.
D. Never install wiring during a lightning storm.

**Lors de l'installation, respectez les consignes de sécuritésuivantes:**

A. Utiliser avec prudence lors de l'installation ou de la modification circuits de télécommunications.
B. Ne jamais toucher les bornes de fil métallique non isolés sauf si le circuit a étédébranché.
C. Ne jamais installer cet appareil dans un endroit humide.
D. Ne jamais installer pendant un orage.


**Global Headquarters**
Watertown, Connecticut USA
Tel: (1) 866-548-5814

SIEMON™
www.siemon.com

For a complete listing of our global offices visit our web site



© 2015 Siemon 2/15 100.21155.00 Rev. B