1 Mounting Panel To Rack

1. Using the supplied mounting screws partially install 2 screws into the lower panel mounting position of the desired rack unit location.
2. locate and Slide enclosure mounting slots on to the screw. (refer fig.1 to 3)
3. Install two upper screws and tighten all screws.




Figure 1




Figure 2




Figure 3




Figure 4
(FHD Flat)





Figure 5
(FHD Anged)

2 Rear Cable Management Bar (Optional all FHD Versions)

1. Install one end of the bar into the slot in the bracket.
2. Slightly bend the other end inward while engaging it into the slot in the opposing bracket.



HPRCMB (Sold Seperately)

Figure 6




Figure 7

1. With the panel installed with all four mounting screws secure, remove the two lower mounting screws.
2. Install the manager bar over the panel and reinstall and tighten the lower mounting screws.




Figure 8




Figure 9

4 Labeling

1. Label stock is Avery 2” x 6” (sold separately)
2. Use the label insert to identify the ports on the panel.




Figure 10

Hubbell Premise Wiring, HUBBELL INCORPORATED (Delaware)
40 Waterview Drive, Shelton, Ct 06484 (800) 626-0005, Fax (860) 535-8328
www.hubbell-premise.com