



CREEP-ZIT™ THREADED CONNECTOR WIRE RUNNING ROD SYSTEM

Creep-Zit™ Replacement Parts

Replacement Creep-Zit™ Male Bullnose Connectors (5 pack)

LS-81-010

CZMBN

Bullnose on one end and a male screw tip connector on the other. Compatible with all Creep-Zit™ rods. Pack of five.



Replacement Creep-Zit™ Female Bullnose Connector (5 pack)

LS-81-020

CZFBN

Bullnose on one end and a female threaded connector on the other. Compatible with all Creep-Zit™ rods. Pack of five.



Replacement Creep-Zit™ Bullnose Connector Pack

LS-81-300

TBCP

Three connectors that are bullnose on one end and a female threaded connector on the other. Three connectors that are bullnose on one end and a male threaded connector on the other. Compatible with all Creep-Zit™ rods. Pack of six connectors.



Replacement Creep-Zit™ Bullnose Connector (5 pack)

LS-81-320

CZCOB

These bullnose connectors are non-threaded replacement tips that must be glued-onto rods using a strong, two part epoxy (not included).



Replacement Creep-Zit™ Female Threaded Connector

These female threaded tips must be glued-onto your rods using strong, two part epoxy (not included). Pack of five.



Replacement Creep-Zit™ Male Threaded Connector

These male threaded tips must be glued-onto your rods using strong, two part epoxy (not included). Pack of five.



Replacement Creep-Zit™ Threaded Connector Pack


Includes five male threaded connectors, five female threaded connectors, and two bullnose replacement tips. All tips must be glued-on to your rods using a strong, two part epoxy (not included). Pack of 12.



Replacement Clear Tube and Yellow End Caps

One clear plastic square tube with two soft yellow rubber end caps.

LS-81-355 CZTUBE



Videos for these products and more are available at GRI and LSDI YouTube:
https://www.youtube.com/channel/UC6DiB2CUXTktCd_xm0MB6VA