Arlington Industries, Inc. 1 Stauffer Ind. Park - Scranton, Pa. 18517

Arlington Cat #

800-233-4717 Fax: 570-562-0646 www.aifittings.com - E-MAIL : sales @ aifittings.com Manufacturers of Quality Electrical Products

FLB3520 Floorbox Kit




WARNING: Make sure power is OFF at main panel box before installing.


Contents: (1) FLB3500 Box

(1) FLB3520 Cover Plate

(1) Gasket

- (1) Gasket Support Plate
- (1) NM94 Cable Connector
- (1) NM95 Cable Connector
- (3) #8 x 1/2" Long Flat Head Screws
- (1) #6 X 1/2" Long Screw
- (3) #6 X 1-1/4" Long Wood Screws
- (1) UL Listed 15A Duplex Receptacle





If you have any questions or if parts are missing from your FLB3520 kit, Please call our Customer Service Department at 1-800-233-4717. Do not call or return this product to your local store or distributor.

Installation Instructions:

- 1. Determine location for the FLB3500 box, being careful to avoid structural framing members.
- 2. At desired location, using 4" diameter Hole Saw, cut hole to depth of approximately 1/2" Then use a 3-1/2" hole saw to cut all the way thru the remaining flooring/subfloor.
- 3. Carefully remove any material that remains between 4" & 3-1/2" hole saw cuts to create a shelf at the desired depth for the FLB3500 box.
- 4. Pull non-metallic type cable and install in FLB3500 box using supplied NM94 or NM95 cable connector.
- 5. Attach box to floor using three #6 x 1-1/4" long wood screws through the U-shaped cut-outs in FLB3500 flange.
- 6. Wire receptacle and install in box. All wiring to be in accordance with State, Local, and National electrical codes.
- 7. Attach supplied gasket support plate to receptacle with #6 x 1/2 Long Screw, and install Gasket.
- 8. Attach coverplate to box using 3 #8 x 1/2" long flat head machine screws

All wiring must be in accordance with National (NEC/CEC), State and Local Electrical Codes.