

```

def _operation = "MIRROR_Z":
    mirror_mod.use_x = False
    mirror_mod.use_y = True
    mirror_mod.use_z = False
elif _operation == "MIRROR_Z":
    mirror_mod.use_x = False
    mirror_mod.use_y = False
    mirror_mod.use_z = True

#selection of the mod -add back the deselected mirror modifier
mirror_ob.select= 1
modifier_ob.select=1
bpy.context.scene.objects.active = modifier_ob
print("Selected" + str(modifier_ob)) # modifier ob is the active ob
mirror_ob.select = 0
end = bpy.context.selected_objects[0]

```

SOFTWARE & FIRMWARE

Panels (Addressable)

Product	Firmware	Software	Resources/Notes
ES-50X and ES-200X	ES Series Firmware v01.03.006 (1.3 MB)	FS-Tools 01.04.010	FS-Tools ES-50X User Guide FS-Tools ES-200X User Guide
MS-9050UD(E) (All Hardware Versions)	Revision 4.1 (298 KB)	PS-TOOLS Remote Upload/Download Utility PPU Wizard Updating Panel Firmware	PPU Tech Bulletin Product Safety Bulletin PS-Tools User Guides
MS-9200UD(E) (Revision 1 Hardware - No USB Connector)	Revision 3.8 (Upgrade Note: Only flash Rev 1 hardware with this firmware) (282 KB)	PK-PLUS Remote Upload/Download Utility (MS-9600 (Pre 4.0 Version), MS-9200UDLS (Pre 4.0 Version) only)	PS-Tools Export/Import FLTB-06-09-04_Using_PPU.pdf
MS-9200UDLS(E) (Revision 2 Hardware - includes USB Connector)	Revision 5.5 (Upgrade Note: Only flash Rev 2 hardware with this firmware) (415 KB)		

MS-9200UDLS(E) (Revision 3 Hardware - includes USB Connector and removable Terminal blocks)	Revision 7.1 (Upgrade Note: Only flash Rev 3 hardware with this firmware) (427 KB)		
MS-9600(E) (All hardware versions)	Revision 2.7 (266 KB)		
MS-9600LS(E) and MS-9600UDLS(E) (All Hardware versions)	Revision 6.2 (427 KB)		

Panels (Conventional)

Product	Firmware/Software	Utilities	Resources/Notes
MS-5UD-3/MS-10UD-7	Revision 2.3 (176 KB)	PS-TOOLS Remote Upload/Download	PPU Tech Bulletin
	Revision 3.1 (178 KB)	Utility PPU Wizard Updating Panel Firmware	PS-Tools User Guides PS-Tools Export/Import

SWIFT® Wireless Products

Product	Firmware/Software	Utilities	Resources/Notes
All SWIFT Devices	SWIFT® Tools	n/a	n/a

Emergency Command Center

Product	Firmware/Software	Utilities	Resources/Notes
ECC-50/100	Revision 1.2 (26.6 MB)	Low Frequency 520HZ Tones: <ul style="list-style-type: none"> • Audio Programming Utility Instructions • Low Frequency 520HZ Steady SKE File • Low Frequency 520HZ Temporal SKE File • Low Frequency 520HZ Steady WAV File • Low Frequency 520HZ Temporal WAV File 	Firmware Update (Doc 1 - Backup Procedure) Firmware Update (Doc 2 - Procedure) Release Notes MNS Backup Conversion Files

FireWatch™ Communicator Series

Product	Firmware/Software	Utilities	Resources/Notes
IP Communicators	IPDACT-2/2UD Windows Configurator Version 5.4 (24 MB)UDPORT Virtual Port	n/a	IPDACT-Configurator Setup Instructions
	Monitoring Software (208 MB)	n/a	Supports upload/download to fire panels equipped with IPDACT-2UD over the Internet or Intranet

VisorAlarm Plus

Product	Firmware/Software	Utilities	Resources/Notes
IP Alarm Receiver	VisorAlarm Manager Teldat Receiver Windows Software (Version 1.3.7) (3.8 MB)	n/a	n/a
	VisorALARM Receiver Firmware Upgrade (Version 10.6.69) (7.6 MB)	n/a	n/a